

B1

TABLE 1

EXAMPLE 4						EXAMPLE 3					
T _L		R _{L1}		R _{L2}		T _L		R _{L1}		R _{L2}	
-1.6 V	+1.2 V	-1.6 V	+1.2 V	-1.6 V	+1.2 V	-1.6 V	+1.2 V	-1.6 V	+1.2 V	-1.6 V	+1.2 V
14.6	72.0	3.3	9.4	3.4	10.0	16.0	79.9	4.6	4.6	2.3	5.7
a*-2.0	-3.0	1.3	6.9	-0.4	3.6	-2.8	-3.3	0.1	14.1	-2.1	8.5
b*-23.6	5.7	1.0	-3.8	4.6	-1.7	-23.2	6.4	-7.7	-12.2	6.3	-5.3

TABLE 2

EXAMPLE 4						EXAMPLE 3					
T _E		R _{E1}		R _{E2}		T _E		R _{E1}		R _{E2}	
-1.6 V	+1.2 V	-1.6 V	+1.2 V	-1.6 V	+1.2 V	-1.6 V	+1.2 V	-1.6 V	+1.2 V	-1.6 V	+1.2 V
10.0	61.2	3.1	9.5	5.4	13.2	10.2	60.2	9.6	12.8	16.0	15.2